














KUH.10264	815x550x16
KUH.10295	815x550x16
KUH.90020	967x130x16
KUH.90083	967x63x16
KUH.40010	967x485x16
KUH.71435 x2	496x713x16
KUH.20090	1000x600x38
KUH.90021	996x95x16




1

6.5x48x16	±8x30mm
	
F2	A
4	8




2

6,4 x 50mm



B

4









O

1




E1


4



3




6,4 x 50mm



B

4




O

1



E1


4






4

$\pm 4.0 \times 45 \text{ mm}$  P4 2	 E9 2	$\pm 3.5 \times 13 \text{ mm}$  P5 8	 T10 4
--	--	--	---




1.



2.






5




6

$\pm 35/0\text{mm}$	$\pm 3.5 \times 13\text{mm}$
	
HG	P5
4	8



7

$\pm 4.0 \times 30\text{mm}$	$L=128\text{mm}$
	
R12	S
4	2

