











	†8x30mm	6,4 x 50mm	†6x42mm	†12/10mm	L=20mm			6.5x48x16	†35/0mm
									
	A	B	B2	C5	D2	E1	E9	F2	HG
	12	8	2	2	2	8	2	4	2
L=450mm	†5/16mm	†5.0x13mm		†4.0x45mm	†3.5x13mm	†3.0x20mm	†4.0x35mm	†4.0x30mm	
									
I5	J3	M	O	O1	P4	P5	P7	R3	R2
1	4	6	1	1	2	10	8-10	4	4
									
									S
									2

ISM-KUH-02413



KUH.30002
KUH.40007






KUH.60006


KUH.10016	815x550x16
KUH.10017	815x550x16
KUH.30002	566x430x16
KUH.40007	567x485x16
KUH.60004	713x585x2,5
KUH.60006	448x528x2,5
KUH.90010	567x100x16
KUH.90011	567x100x16
KUH.90015	599x95x16
WST.0139	450x80x12
WST.0140	450x80x12
WST.0082	518x80x12
KUH.20009	600x600x28
KUH.71223	133x596x16
KUH.70546	576x596x16

1




$\pm 8 \times 30 \text{ mm}$  A 4	 O1 1	$\pm 12 / 10 \text{ mm}$  C5 2
---	--	--



2







$\pm 6 \times 42 \text{ mm}$  B2 2	 O1 1
---	---










3

$L = 20 \text{ mm}$  D2 2
--






4












5



L=450mm	φ3.5x13mm
I5	P5
1	6





6.5x48x16  F2 4	±8x30mm  A 8	L=450mm  I5 1	±5.0x13mm  M 6
--	---	--	---








7

6,4 x 50mm		
		
B	O	E1
4	1	4





8







6,4 x 50mm		
		
B	O	E1
4	1	4

9





10





11

$\pm 4.0 \times 45 \text{mm}$  P4 2	 E9 2	$\pm 4.0 \times 35 \text{mm}$  R3 4
---	---	---



12

$\pm 5/16 \text{mm}$  J3 4



13

+4.0x30mm





R2

2



S

1



14

+35/0mm



HG






2

+3.5x13mm






P5



4



φ4.0x30mm



KUH.70546



KUH.70546

