



HUB 60 Z





†8x30mm A 8	6,4 x 50mm B 8	E1 8	6.5x48x16 F2 4	L28 2	O 1	†4.0x45mm P4 2	†3.5x13mm P5 16	†3.0x20mm P7 8-10	T10 4
---	--	---	--	--	--	--	---	---	--














KUH.40008

KUH.10009	815x550x16
KUH.10010	815x550x16
KUH.40008	567x485x16
KUH.60007	585x115x2,5
KUH.70549	596x110x16
KUH.90010	567x100x16
KUH.90011	567x100x16
KUH.90015	599x95x16
KUH.20009	600x600x28


1

$\varnothing 8 \times 30 \text{ mm}$  A	$6.5 \times 48 \times 16$  F2	 L28	$\varnothing 3.5 \times 13 \text{ mm}$  P5
8	4	2	8




2

6,4 x 50mm



B

2







O

1



E1

2



3

6,4 x 50mm





B

2








O




1



4




5




6

6,4 x 50mm



B

6




O

1



E1

6



B


B

KUH.40008

B

KUH.10010

E1



B

7


#3.0x20mm




P7

8-10

KUH.60007



P7



P7

7mm


P7

P7

P7

A=B

B A



3.5x13mm



P5

8



T10

4

