






ISM-KUH-02405








KUH.10020 x2	580x290x16
KUH.30001	466x250x16
KUH.40001 x2	467x276x16
KUH.60013	576x485x2,5
KUH.71434	576x496x16



KUH.30001





KUH.40001

$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 4.0 \times 30 \text{ mm}$  P8	 K
8	4	2




2

4	1	4
		
A	O	E1








3





4	1	4
		
A	O	E1












4



5





6



7











±5/16mm

J3
4



8

±35/0mm	±3.5x13mm
	
HG	P5
2	4



9

4.0x30mm  R12 2	L=128mm  S 1
--	---

