



ISM-KUH-02407









KUH.30005

KUH.40011









KUH.10020 x2	580x290x16
KUH.30005	966x250x16
KUH.40011 x2	967x276x16
KUH.60016	576x491x2,5
KUH.60017	576x491x2,5
KUH.71434 x2	576x496x16

$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 4.0 \times 30 \text{ mm}$  P8	 K
8	4	2




2

+8x30mm		
		
A	O	E1
4	1	4







3







+8x30mm		
		
A	O	E1
4	1	4













4



5





6





7

$\pm 5/16$ mm 
J3
4






8

$\pm 35/0$ mm 	$\pm 3.5 \times 13$ mm 
HG	P5
4	8



9



10

$\varnothing 4.0 \times 30 \text{ mm}$  R12 4	L=128 mm  S 2
---	--

