























Assembly Instruction

 <p>Ax1</p>	 <p>Fx5</p>	<p>1</p>  <p>G</p> <p>H</p> <p>D</p> <p>F</p>	<p>2</p>  <p>J</p> <p>N</p> <p>M6*35mm</p> <p>M6*20mm</p> <p>N</p> <p>I</p> <p>M</p>	<p>3</p> 
 <p>Bx1</p>	 <p>Gx1</p>	<p>4</p>  <p>K</p> <p>M</p> <p>M8*30mm</p>	<p>5</p>  <p>L</p> <p>M</p>	<p>6</p> 
 <p>Cx2</p>	 <p>Hx1</p>			
 <p>Dx1</p>	 <p>Ix4</p>			
 <p>Ex1</p>	 <p>Jx6</p>			
	 <p>Kx2</p>			
	 <p>Lx2</p>			
	 <p>Mx1</p>			
	 <p>Nx10</p>			
	 <p>Ox1</p>			
	 <p>Px1</p>			